

C225 was added. its value is selected for frequency, determine by inspection C226 and C227 are selected for frequency, determine by inspection.

Serial Numbers of units affected by this modification:

20,36 through 38,51,55,70,78,83,110,143,205 through 226,235 through 241, through 251,115 and 116,130,138 and 139,230, and 253 through 267.

Additional Changes:

C7 was changed to a 470 pf mica from a 220pf mica to adjust gain.

C69 was changed to a 470 pf mica from a 470 pf disc to improve stability.

C113 was changed to a 220 pf mica from a 470 pf mica to adjust stability.

C114 was changed to a 68 pf mica from a 68 pf disc to improve stability.

C122 is not used most of the time but when it is, it is a 10 pf mica.

C203 was changed to a .1 disc from a .1 disc to increase decoupling.

C206 was changed to two .003 mica in parallel from a .005 disc to increase drive.

C222 was changed to a .0015 mica from a .001 disc to increase drive.

R302 and R303 were changed to 2.2K ohm from 6.8K ohm to decrease current drive.